



TECHNICIANS IN PREVENTION · PARTNERS IN PREVENTION · PARTNERS IN PREVENTION · PARTNERS

## SAFETY ALERT!

### 3-Piece Wheel Assembly Service Work

This safety alert is a result of a recent fatal incident within our industry involving an employee working on a 3-piece wheel assembly.

The following safety procedures can reduce the frequency and/or the severity of the loss:

- All components of a multi-piece rim **MUST** be in place prior to inflation – especially the lock ring (safety ring)
- Everyone **MUST** remain out of the trajectory zone when inflating any tire
- A remote airline **MUST** be used during inflation
- All technicians **MUST** be trained to safely perform the job/tasks

If you are unsure about a process or task, **STOP** and ask for clarification or help

Loss of life, injury, and property damage can be prevented. Training staff to follow proper procedures is critical to ensuring everyone's safety. Please share this bulletin with your employees.

**Let's be careful out there!**



partners in prevention



Knowing your business matters.